

Annexure D

BUILDING SAFETY CERTIFICATE

No. 60/stry-AE.I

Dated: 26/04/2025

It is certified that the existing buildingBaluni School of Competency.....(name of the building or premises) atKhasra No: 124 & 125.....Majra.....Pahimpur.....tehsil - Mathura.....(address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2	—	—	—	—	—

The building is owned/occupied by.....Baluni Education Society.....(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Assistant Engineer (Name of Department/ Govt.) on....26/04/2025..(date of inspection) in the presence ofRishi Singh, Baluni School of Competency (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from. 26/04/2025 for a period often (10) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Regular Maintenance should be done as per specification.
2. Structural stability after 10/5yr. should be checked by an engineer.
3. Fire safety should be checked by fire officer.
- 4.

Issued on26/04/2025.... atMathura..... by Assistant Engineer

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : Sandeep Kumar Tewari

Designation : Assistant Engineer

Name & Address of Department/ Office: P.D., P.H.D


सहायक अभियन्ता

गन्तीय खाड लो० नि० विभा०

मथुरा